

## SIMPLIFIED LESSONS IN CARE OF AUTOMOBILE

Expert Frederick C. Guerrich Describes Functions of "Bearings" or "Bushings."

### HOW FRICTION IS REDUCED

How to Remedy Play of Parts When Bearings Are Worn—Problems of Many Automobile Owners Solved Readily by Man Who Knows.

AUTO LESSON NO. 110.

(Copyright, 1918, by Fred C. Guerrich.) There are innumerable parts of the automobile which rub or revolve on other parts, such as the crank shaft on its supports, the crank pins in the ends of the connecting rods, the wheels on their axles. As these parts rub on one another, there will be wear and the generation of heat, or, in other words, friction.

Friction cannot be eliminated, but it can be greatly reduced by lubrication, and by making the rubbing surfaces of materials whose tendency to wear and heat is low, as engineers would say, whose "co-efficient of friction" is low. Lead and bronze are such materials, the former being the better, but because of its softness, it is mixed with other metals, such as tin, antimony and copper, in which case it is known as "white" or "Babbitt" metal.

To overcome the friction, therefore, some device such as a properly placed piece of Babbitt or bronze, or a set of rollers or rolling balls, is usually placed between the rubbing parts. These devices are called "bearings" or "bushings."

Parts can move on one another in three ways, namely: they can move in a straight line, one on the other, as, for example, the pistons in the cylinders, one can revolve in or about the other, as the crank shaft in its supports, or as the wheels on their axles, and the shaft can revolve against a support.

In the automobile where the parts simply slide and revolve, as, for example, the pistons and the crank shaft, given, the pressures and, therefore, wear, if they are well lubricated, are comparatively small, so, as a rule, no special bearing is used.

By far the greatest amount of moving parts move as given in the second case; that is, a shaft revolves in another part, that is, a wheel or similar part revolves about a stationary shaft. Where the shaft is small in diameter and the movement little, the bearing is generally nothing but a "sleeve" or roller made of some anti-friction metal, as bronze or Babbitt, and is called a "bushing," as, for example, the wrist-pin bushings and universal-joint bushings. Where the shaft is of any size and where the movement is fast, the pressure comparatively high, the bearing is called a "journal bearing." In the engine, the journal bearings are almost always made in two parts, for the sake of easy removal, and are made of bronze or of Babbitt. The Babbitt or bronze bearings have a very low friction, but by the use of ball or roller bearings the friction and wear can be still further reduced, as when they are used there is practically no rubbing, as the balls or rollers simply roll between the two surfaces. Either ball or roller bearings are used in practically all places other than the engine.

Where the movement is as given in the third case, namely, when the end of a shaft or a flange fastened to the shaft revolves or spins on a bearing surface, the bearing is said to be subjected to a thrust and the bearing is called a "thrust bearing." This bearing is placed between the shaft and the bearing surface, which is placed between the clutch throw-out, or shift collar and the fork, or between the bearing surface, the bearing is said to be subjected to a thrust and the bearing is called a "thrust bearing." This bearing is placed between the shaft and the bearing surface, which is placed between the clutch throw-out, or shift collar and the fork, or between the bearing surface, the bearing is said to be subjected to a thrust and the bearing is called a "thrust bearing."


### HOW TO REMEDY PLAY

#### WHEN BEARINGS ARE WORN

When bearings of this style become worn, the resulting play can be taken out by removing or filing on the "shims," which are shown as "B" in Figure 2. These are separators made up of a bundle of very thin leaves of brass, or of one heavy piece. When the play is taken out by removing one of the leaves, while, if the latter, a little is filed off it. Adjusting of the engine bearings should be done by experienced mechanics only, as the bearing must fit the shaft snugly, yet not bind while the nuts of the bolts which hold the two halves of the bearing together must be as tight as they can be without breaking.

When much play must be taken out of the bearings, or when new bearings are put in, they will have a "scraped" surface. This is done by smoothing some Prussian blue on the shaft, and then revolving it in its bearings. The Prussian blue will thus mark the high spots of the bearings, which high spots must then be scraped off, and the process repeated, time and time again, until practically the entire surface of the bearing touches the shaft, fitting or running in bearings, care must be taken to have the shafts, etc., in line. Thus when the main bearings of a crank shaft are fitted the

## Function of Bearings Shown



fixed half of the bearings must be first scraped in, and tests made repeatedly to see that no bearing is lower or higher than the others. If this is not done the bearings when tightened will tend to bend the shaft. In Figure 3 I have shown the middle bearing out of line with the end bearings. Obviously, when the caps are tightened the shaft will be bent. It is for this reason that the novice should not attempt to fit the main bearings, as it takes skill and experience to do this properly.

In fitting the main bearings the half-time gears should first be studied to see if they should be brought closer together or farther apart. Failure to do this will mean a "growl" of the gears. Unfortunately, few mechanics do this, and often by taking too much from the fixed half of the bearing will bring the gears too close together.

### QUESTIONS AND ANSWERS

Q. I would like to know the cause of a few motion on low speed on a Ford touring car.

A. While a rise in the engine may be to blame, it is most likely that the low speed band is worn and slipping. An examination of the band will indicate the cause.

Q. Three months ago I purchased a new (1917) car. Several weeks afterward the car developed a spark plug trouble. After every run of from twenty to fifty miles the motor missed firing. I have had the car at the service station five times but they had the engine down and now rings are not in, but after fifty miles run the same old trouble developed. I had a friend take the top of this motor and we found strokes of oil on the walls of the cylinders. I am using oil of medium caliber for the motor and tried a heavier oil, but no improvement resulted. The pistons do not seem to be tight. He moved the pistons sideways in all directions. The bore is three and one-quarter and stroke five and one-half.

The car is in other respects a fine machine. Can you suggest a remedy?

A. If the play of the pistons was found while they were cold then it is right that they should be so, as a certain amount of clearance must be allowed to permit of expansion of the pistons when they become hot. I believe that the oil streaks are right also, unless oil has gathered on the piston head, not in, but after fifty miles run the same old trouble developed. I had a friend take the top of this motor and we found strokes of oil on the walls of the cylinders. I am using oil of medium caliber for the motor and tried a heavier oil, but no improvement resulted. The pistons do not seem to be tight. He moved the pistons sideways in all directions. The bore is three and one-quarter and stroke five and one-half.

While the trouble may be due to the oil setting past the rings it is quite possible that the trouble is due to the fault sprig points may not be correctly set, or there may be a slight short circuit, or a poor connection in the primary circuit. In view of the fact that apparently all has been done that can be done to overcome oil trouble it might be well to check up on the ignition system and also the compression, as regards valves.

Q. I am much interested in your articles on the automobile. I have a (1917) car with (1) carburetor, and (2) I don't know what I have cleaned the carburetor every ten hours. Please advise how to stop the leak.

A. If the leakage is only after the engine has been stopped, then it probably is due to the seal which is condensed on the manifold flowing back. If with cold weather, it probably increases due to the heat coming too high. Take off the heat chamber top and see if leakage does not occur, and then see if leakage stops. Try again, remembering how many

times you have cleaned the carburetor.

Q. I have a (1917) car which runs fairly well only when I start the engine it seems to choke and often stops.

A. When an engine is cold the gasoline condenses on the manifold, but the condensed gasoline will be made to flow to the cylinders by the friction of the cranking. Any sudden change in the carburetor, such as the sudden opening of the throttle liquid, and either cause to run back to the carburetor, or cause too large an amount of the gas to rush into the cylinders. This will cause the choking and stopping as mentioned by you.

A friend of mine has a (1917) car

with a thing he calls a thermostat and says it makes his car run fine even when cold. What is this, and would it pay to put one on my (1917) car?

A. The thermostat is a device which will expand greatly when heated. It is used in a number of cars to force the cooling water to become warm quickly when the engine is started. Its operation is as follows: The thermostat, which is placed at the top of the cooling system, is contracted, and which valve shuts off the water between the engine and the radiator. Thus only a small amount of water is used for cooling, but as the engine becomes heated, the thermostat gradually expands and so gradually opens the valve between radiator and engine. Thus the engine will become warm and the troubles of a cold engine are greatly lessened.

By constant opening and closing the valve, or by keeping the valve partly open, the thermostat will keep the temperature of the water fairly uniform, which means efficiency. They are good, but you will probably find the cost of installing one too great for the advantage gained.

doing their bit in the best possible way by presenting themselves for induction to the air service trade-test board at Atlanta, Ga.; St. Louis, Mo.; Detroit, Mich.; Denver, Col.; Boston, Mass.; Chicago, Ill.; New York City; San Francisco, Cal. In order that they may be inducted by these boards. The following data concerning the draft status is necessary: Address of local draft board, order and serial number, classification and division.

The "Miscellaneous For Sale" column on the Want Ad pages offer you great opportunities to dispose of used but useful things at a good price.

## JORDAN SPORT MARINE

At last—a car that is absolutely complete from motor to extra Silverton tires and extra 224 wire wheel chassis contains only parts of the finest standard makes. The Jordan Motor Car Co., Cleveland, Ohio.

## USL BATTERY SERVICE STATION

W. M. REYNOLDS  
2035 W. Broad Street,  
Richmond.

## MECHANICS MAKE ACES EFFECTIVE

(Continued From First Page.)  
terminations two or three nights a week.  
Mechanics are needed in the air service, needed badly and at once, and all men who have had experience as motor mechanics, blacksmiths, cabinet-makers, carpenters, chauffeurs, copper-smiths, electricians, fabric workers, instrument men, machinists, metal workers, motorcyclists, propeller makers, vulcanizers or welders will be

## GATES HALF-SOLE TIRES

"If it  
Isn't a  
Gates  
It Isn't  
A Half  
Sole"

Not sewed on.  
Not vulcanized on.  
Not a retreaded process.  
Double your mileage.  
Guaranteed puncture-proof.  
Oversize your tires.  
Take the worry out of driving.  
Yet cost only half as much.  
You owe it to yourself to investigate this remarkable tire product.

## International Rubber Sales Co.

1020 West Broad Street.

## GATES HALF-SOLE TIRES




## TOURING BODIES

A few of the latest models in stock for IMMEDIATE DELIVERY. Prices on application.

## RICHMOND MOTOR CO., Inc.

TENTH AND BROAD STREETS,  
RANDOLPH 407. RICHMOND, VA.

## Worm-Drive Eliminates Gears



Day-Elder Trucks Are Worm-Drive, and They Are the Trucks That Are Giving Such Unusual Satisfaction

When you buy a truck that has worm-drive, you are making for efficiency in every way, because worm-drive eliminates many unnecessary gears, eliminates friction, eliminates loss of power and gives more power than is possible in chain or internal gear drives. And the best part of these statements is that we are ready to prove it to you, and prove it so you will be convinced that you cannot afford to buy any other kind of drive, even if you do not buy a Day-Elder truck.

However, in D-E Trucks You Get the Same Features That Will Be Found in Trucks From \$300 to \$500 More

Once you have become convinced that worm-drive is the one best suited for trucks, and have seen the Day-Elder Truck, with its superior features, you will decide that you cannot, in justice to your pocket-book, buy any other.

## Try and Get These Features on Any Truck at the Prices of D-E'S

Continental or Buda Motors.  
Zenith Carburetors.  
Bush Tank Castings.  
Heavier Wheels and Frames.  
Roller Bearings.  
WORM-DRIVE.

Really, we cannot tell you the many points about these Trucks with cold type—you must come and let us demonstrate the size you want (and we have one just suited to your business) and see for yourself how they measure up with others at these prices. AND WE WILL NOT COMPEL YOU TO BUY IF YOU DO NOT WANT TO, NEITHER WILL YOU BE UNDER ANY OBLIGATION.

1½ tons ..... \$1775  
3 tons ..... \$2750  
2 tons ..... \$2075  
6 tons ..... \$4500

## KLINE KAR Sales Co., Inc.

RUSSELL H. RAWLINGS, President.

612 West Broad Street.

## WE SPECIALIZE ON Repairing High Grade Cars

AND STARTING AND LIGHTING SYSTEMS.

All Work Guaranteed.

## J. R. LAYNE

Phone Madison 1548. 1200 West Broad Street.

## Immediate Delivery



LATE MODEL—USED

Trucks—Runabout—Ten Truck

## Richmond Motor Co., Inc.

BROAD AT TENTH.

Phone Randolph 407.

Richmond, Va.

## One to Pittsburg! One to New York!

Delivery of White Trucks made by driving trucks to these points shows the extraordinary condition created by the government's demand for White Trucks.

The man or firm that secures the only remaining White Truck still on our floor can be considered lucky, for this will probably be the last we will receive until the first of the year.

## The \$25,000 Service With WHITE TRUCKS

Congested freights do not interfere with the supply of White repair parts, as these are coming through in large quantities, and are available for government trucks as well as other users. The largest service department in the South devoted wholly to trucks.

## Smith & Hicks, Inc.


Tel. Mad. 971, 972, 973.  
12, 14, 16 N. Fifteenth Street,  
Entire Building.

Made by the  
White Company,  
Cleveland, O.



## Davis Essential Sixes—

Are Selling Fast In and Around Richmond Because They Are Extra Value and Their Performance Is All That Could Be Desired.



There is absolutely no way to adequately describe any automobile, much less describe this wonder car, with cold type. All we can hope to do is to tell you the special features and try to get you interested in the Davis enough to come and let us show you how it outclasses anything at the price on the market to-day. Sales are mounting higher and higher every day, and there must be a reason besides salesmanship—that reason is quality and right prices.

## Heed This Warning—

Automobiles are going to be scarce and high in price, and our advice to you is to get your car now, rather than be disappointed later, as you are bound to be with conditions as they are on account of the recent government order to all manufacturers.

## READ—

Luxurious Lines.  
Luxurious Appointments.  
Continental Motors.  
Deleto Starting, Lighting and Ignition.

Stromberg Carburetors.  
Any Hill on High.  
17 Miles to the Gallon.  
5,000 Miles on Tires.

Come—Look—Be Conquered! That's What Happens When a Prospective Buyer Sees the Incomparable Davis Essential Six.

## Rawlings Motors

Incorporated,

Russell H. Rawlings, Pres.

818 W. Broad Street.


## Immediate Delivery Premier Touring Cars

We are prepared to deliver immediately several of these splendid cars.

## Capital Motor Corp.

319 West Broad Street.

## White-Truxtons



Regular 2-ton White Truck Chassis (motor rebuilt by White factory mechanics).

2 Tons Capacity, Complete with Cab and Windshield.  
\$1350 Delivered in Richmond.  
3-Ton White-Truxtons—\$1750 delivered.

H. P. Powell, Sales Manager, Tel. Madison 5590, Service Station and Office, 18-20 S. 15th St.

## Commercial Motors Inc.